

## Site Construction Update - Week of 11-Jan-2021 to 16-Jan-2021

1. Dewatering wells active throughout site (settlement tank & discharge point located at North side of Galleria Mall)
2. Crane pad installation works (formwork & concrete placement)
3. On-going bulk excavation to depth of 2<sup>nd</sup> row tiebacks, & associated daily exporting
4. Tieback installation works along North, East, & Southwest radius shoring walls
5. Install first level corner braces at Northeast corner of site