

Site Construction Update - Week of 18-Jan-2021 to 23-Jan-2021

1. Dewatering wells active throughout site (settlement tank & discharge point located at North side of Galleria Mall)
2. Completion of crane pad installation works at Southeast section of site
3. On-going bulk excavation to depth of 2nd row tiebacks, & associated daily exporting
4. Tieback installation works along North, East, & Southwest radius shoring walls
5. Install first level corner braces at Northeast corner of site
6. Demobilization of BG40 shoring rig